








Vigor Router 3.5G Modems / Mobiles Support List



The following 3.5G modems / mobiles have been tested with Vigor2110 series , Vigor2130 series, Vigor2710 series, Vigor2800 series , Vigor2820 series , Vigor2830 series , **Vigor2850 series , Vigor2910 series , Vigor2920 series, Vigor2955, Vigor3100 series , Vigor3200 series , VigorPro 5510 series, VigorIPPBX 2820 series, VigorIPPBX 3510** and Mandy other standard 3.5G modems / mobiles will also work; please download latest Firmware for your Vigor router.


















Note: If your 3.5G modem is not in the compatible list, please check if the router firmware version is the latest version or not. If not, please download and install the newest one. After finishing the installation, if the router still can not work, please capture the syslog and contact with us.

- (1) Check /download the Firmware version: <http://www.draytek.com/user/SupportDownloads.php>
- (2) Configuration fro 3G connection: <http://www.draytek.com/user/SupportFAQDetail.php?ID=1943>
- (3) Setting the Syslog: <http://www.draytek.com/user/SupportTroubleDetail.php?ID=10>
- (4) Download Syslog Utility: <http://www.draytek.com/user/SupportDLUtility.php>
- (5) If your modem works fine with Vigor router but not listed in current compatible table, please contact with DrayTek service center.
- (6) ■ : This symbol indicates that the modem or mobile phone has been tested and **is supported** by the router.
◎ : This symbol indicates that the modem or mobile phone has not been tested but **might be supported** by the router.
△ : This symbol indicates that the modem or mobile phone has been tested but **is supported** by the router with **specific circumstance**.
∅ : This symbol indicates that the modem or mobile phone has been tested and **is not supported** by the router.
Please contact support@draytek.com if you have any problem.

																		
Brand	Module	Vigor2110	Vigor2130	Vigor2710	Vigor2750	Vigor2800	Vigor2820	Vigor2830	Vigor2850	Vigor2910	Vigor2920	Vigor2955	Vigor3100	Vigor3200	VigorPro 5510	VigoriPPBX 2820	VigoriPPBX 3510	VigorFly 200
4G system	XSPUG P3									■	⊙							
Aiko	Aiko 76E									■	⊙							
	Aiko 83D						■			■	⊙							
Alfa	Fly3G			■			■			■	■		■					
Amoi	Amoi H01									■	⊙							
	ADU-300									■	⊙							
AnyDATA	ADU-500A	■	■	■		■				■	■		■	■		■	■	■
	ADU-510A	■	■	■		■	■			■	■		■	■		■	■	■
ASUS	ASUS T500									■	⊙							
	Bandluxe C100									■	⊙							
	*Bandluxe C100S (See Remark one)									■	⊙							
BandRich	Bandluxe C120									■	⊙							
	Bandluxe C170									■	⊙						■	
	Bandluxe C270																■	
	Bandluxe C321	■		■		■								■		■	■	■
	Bandluxe C331	■	■	■		■				■	⊙				■	■	■	■
BigPond	BigPond Next G Wireless Broadband USB Mobile Card					■				■	⊙							
	BigPond Next G Wireless Broadband USB Modem					■				■	⊙							
	C-motech CDU-550																	
C-motech	C-motech CNU-680	■		■		■	■			■	■		■		■			
	C-motech D-50									■	⊙		■					
DETrade	DET-US3G5									■	⊙							
D-Link	DWM152									■	⊙							
	DWM156						■			■	■							
	DWM156 A2									■	⊙							
	DWM156 A3									■	⊙							
	Huawei E150	■	■	■		■	■	■		■	■		■	■		■	■	
	Huawei E153	■		■			■	■		■	■			■		■	■	■
	Huawei E156G	■		■		■	■	■		■	■		■					
	Huawei E160									■	⊙							
	Huawei E160E						■	■		■	■							
	Huawei E160G	■		■		■	■	■		■	⊙							
	Huawei E161						■	■		■	⊙							
	Huawei E169	■		■		■	■	■		■	■				■			
	Huawei E169u						■	■		■	⊙							
	Huawei E171	■	■	■		■	■	■		■	⊙	■		■	■	■	■	■
	Huawei E172					■				■	⊙							
	Huawei E173		■	■		■	■	■	■	■	■		■			■		■
	Huawei E1762	■		■			■	■										
	Huawei E176c						■	■		■	⊙							
	Huawei E176G		■															■
	Huawei E180	■	■	■		■												
	Huawei E219	■		■		■	■	■		■	⊙				■			
	Huawei E220	■	■	■		■	■	■		■	■	■	■		■	■		■
	Huawei E230					■				■	⊙							
	Huawei E270									■	⊙							
	Huawei E272	■				■	■			■	■				■			

																		
Brand	Module	Vigor2110	Vigor2130	Vigor2710	Vigor2750	Vigor2800	Vigor2820	Vigor2830	Vigor2850	Vigor2910	Vigor2920	Vigor2955	Vigor3100	Vigor3200	VigorPro 5510	VigoriPPBX 2820	VigoriPPBX 3510	VigorFly 200
Huawei	Huawei E353		■	■			■		■		■			■		■		■
	Huawei EC226 (CDMA2000)	■				■	■			■	■				■			
	Huawei EC228	■		■			■			■	■							
	Huawei EC306						■	■		■	■	△			∅		■	
	Huawei Smartone-Vodafone E272									■	◎							
	Huawei E1550	■				■		■		■	■							
	Huawei E1750		■				■			■	■							
	Huawei E1750C	■	■	■		∅	■	■		■	■		■	■	■	■		■
	Huawei E1756C				■			■		■	◎							
	Huawei E1752		■					■			■							
	Huawei E1820	■	■					■		■	■							
	Huawei E2010	■	■	■														
	Huawei K3765		■								■	■						
	Huawei K4505		■	■	■					■	■	■						
Huawei Zoom 4595								■										
Mobidata	MBD-220HU	■		■				■			■			■				
MOMODESIGN	MD-@									■	◎							
Novatel Wireless	Ovation™ MC760D		■							■	◎							
	Ovation™ MC950D						■			■	◎		■					
	Ovation™ MC990D						■			■	◎	■			■		■	
	Ovation™ USB720									■	◎							
	Ovation™ USB760									■	■		■					
Option	Option GlobeSurfer i CON * (See Remark two)																	
	GlobeSurfer i CON 7.2						■			■	◎				■		■	
	GlobeTrotter G11505		■				■			■	◎							
	Icon 225	■		■			■			■	■				■		■	
	Icon 431	■		■			■	■				■			■	■		
	Icon 505									■	◎							
Icon G10301																■		
Pantech	UM150	■		■			■			■	◎	■			■			
	UM175VW					■	■			■	◎		■		■			
Qisda	Qisda H21					■				■	◎							
Sierra	Sierra 309	■	■	■						■	◎							
	Sierra 597	■		■			■											
	Sierra 875U									■	◎		■					
	Sierra AC310	■	■	■														
	Sierra AC312U * (See Remark three)	■	■	■						■								
	Sirerra Aircard 880U					■	■			■	◎							
	Compass 885									■	◎							
	Compass 888	■	■	■						■	◎							
	Compass 889	■	■	■														
Wireless USB 307									■									

																		
Brand	Module	Vigor2110	Vigor2130	Vigor2710	Vigor2750	Vigor2800	Vigor2820	Vigor2830	Vigor2850	Vigor2910	Vigor2920	Vigor2955	Vigor3100	Vigor3200	VigorPro 5510	VigoriPPBX 2820	VigoriPPBX 3510	VigorFly 200
Sony Ericsson	Sony Ericsson MD300									■	⊙							
Telstra	Telstra TurBO / NexT G 3G USB Modem						■			■	⊙							
Vodafone	Vodafone K3520-Z							■									■	
	Vodafone K3565	■		■			■			■	■	■	■		■			
	Vodafone K3565-Z						■	■		■	⊙							
	Vodafone K3565 rev 2			■			■						■		■	■		
	Vodafone K3715						■			■	⊙							
	Vodafone K3760						■											
	Vodafone K3765-Z	■		■														
	Vodafone K4605							■			■							
XS Stick	XS Stick W12									■	⊙							
ZadaCOM	ZadaCOM 3G+ 7.2									■	⊙							
Zapp	Zapp Telemodem Z020									■	⊙							
Zoom	Zoom 4595			■			■											
ZTE	ZTE AC580									■	⊙							
	ZTE AC2726						■			■	⊙				■			
	ZTE AC5710									■	⊙		■					
	ZTE AC8700						■			■	⊙		■					
	ZTE AC8710						■			■	⊙							
	ZTE K3571-Z	■		■				■		■	■							
	ZTE MF100	■	■	■			■			■	⊙	■			■			
	ZTE MF110	■					■	■	■		■			■				
	ZTE MF112	■	■	■			■			■	⊙							■
	ZTE MF180									■	⊙							
	ZTE MF190						■			■	■							
	ZTE MF622									■	⊙							
	ZTE MF626	■	■				■	■		■	■					■	■	■
	ZTE MF627	■	■							■	⊙							■
	ZTE MF627 plus									■	⊙							
	ZTE MF633			■			■	■		■	■		■					■
	ZTE MF636	■		■			■	■		■	■			■				■
	ZTE MF636DB	■	■	■			■			■	■							■
	ZTE MF637	■		■			■			■	⊙							
	ZTE MF639			■														
ZTE MF662	■		■			■			■	⊙								

Remark

1. BandRich Bandlux C100S : NOT USE in America Zone because C100S lacks 850/1900MHz .
2. Option GlobeSurfer i CON : Only for France and Poland.
3. Sierra AC312U : Firmware version N2_0_8_5ap. (<http://www.sierrawireless.com/>)